



1 Notify all employees about the required lockout



2 Shut down equipment using normal stopping procedure



3 Locate and isolate equipment from all energy sources



9 Once work is completed, notify all employees



4 Release any stored energy



8 Remove the lockout device



5 Lockout all switches and controls with assigned locks and tags



7 Perform servicing



6 After ensuring that no personnel are exposed, operate the normal operating controls to make sure equipment won't operate

RETURN EQUIPMENT TO 'OFF' STATE AFTER TEST



¿Cuánto vale su vida?

Bloqueo y Etiqueta

El bloqueo y etiqueta son procedimientos de seguridad para aislar energía y proteger a empleados contra heridas cuando le están haciendo mantenimiento, servicio y solucionando problemas a maquinarias.


¿Cuándo lo debería de usar?

Bloqueo y etiqueta es requerido cuando uno está trabajando en maquinaria o aparatos donde se pueda prender inesperadamente o, pueda haber liberación de energía almacenada.

Las cinco causas fatales que resultan de heridas relacionadas con bloqueo y etiqueta

1. Fallar en parar la maquinaria
2. Falta de desconectar la conexión a la fuente de energía
3. Falta de purgar la energía residual
4. Volver a prender la maquinaria accidentalmente
5. Fallar en no despejar las áreas de trabajo antes de reiniciar

Se estima que cumplir con los procedimientos de bloqueo y etiqueta previene 120 fallecimientos y 50,000 heridas cada año. (ESFI.org)



YOUR LIFE DEPENDS ON IT